



Demontage kuipdelen ST1300





Succes mensen!




Naar voren toe losklappen!















A close-up photograph of a blue motorcycle engine cover. The cover is made of metal and features a series of horizontal ridges on the left side. Several bolts are visible, securing the cover. A blue speech bubble with white text is overlaid on the right side of the image, pointing towards the bolts. The text inside the bubble reads: "Opm. dit zijn niet de originele clips! Die van Honda moet je Los trekken!".

Opm. dit zijn niet de
originele clips!
Die van Honda moet je
Los trekken!







Klikpen!





klikpennetjes


schroefjes



schroefje
links&rechts




Sensor!!





Kuipdeel links
is nu los en kan
verwijderd worden!

A close-up photograph of a vehicle's brake assembly. A black cable is connected to a small, circular sensor mounted on a metal bracket. The sensor is positioned near the brake pads and rotors. A blue speech bubble with the text "Sensor!!" points to the sensor. The background shows various metal components of the brake system, including the brake pads and the brake disc. A label on the right side of the image reads "ABS & DUAL Brake System".


Sensor!!




inbus

m8

m8





Conector

Kuipdeel!

